ANNUAL INDEX

The following code of symbols is used to identify regular department locations in the subject page listings: CCM, Color Countermeasures; Sym, Symfact®; TE, Notes on Test Equipment; TS The Troubleshooter; and VSS, Video Speed Servicing.

AGC

Color receiver, circuitry in ....Sep 51
Filter capacitor, shorted causes video overload, Admiral Chassis G-1263-1 ....VSS Feb 6
Forward keyed transistor system, analysis of ....Oct 4
Keyed systems ....Dec 30
—hybrid designs ....Dec 33
—noise-cancelling effects ....Dec 31
—servicing procedures ....Dec 31
—transistor circuits ....Dec 33
Overload picture on strong signal, Motorola Chassis TS-912 ....VSS Jul 14
Transistor TV, employed in ....Jun 62

ANTENNAS

Installing for color ....Apr 60
Lead-in ....Feb 24
Selling ....Apr 58

AUDIO SYSTEMS

Equipment for servicing ....Mar 20
—AC VTVM ....Mar 20
—books concerning ....Mar 22
—distortion analyzers ....Mar 21
—phase checker ....Mar 22
—signal generator ....Mar 20
—wattmeter ....Mar 22
High-quality systems, servicing ....Aug 32
—components ....Aug 32
—distortion measurement ....Aug 38
—frequency response ....Aug 58
—sensitivity measurement ....Aug 38
—separation measurement ....Aug 58
—system analysis ....Aug 33
—tuner bandpass measurement ....Aug 38
—turntable tests ....Aug 60
Intercom and music distortion systems, installing ....Dec 24

AUTO RADIOS

High end of band inoperative when receiver installed in car, Pontiac Model 983873 ....TS Jun 56

BOOK REVIEWS

Audio Amplifier Design ....Dec 62
Communications Electronics Circuits ....Jan 37
Directory of Electronic Circuits ..Jun 54
Electricity One through Electricity Seven ....May 60
Electron Tubes ....Feb 18
FET Circuits ....Dec 36
How to Build Speaker Enclosures ....Mar 77
Power Supplies for Electronic Equipment ....Jul 53
Single Sideband: Theory and Practice ....Oct 41
Transistor Basics: A short course Aug 72
Understanding UHF Equipment ..Sep 42

BUSINESS

Advertising, measuring the results of ....Aug 44
—attitude advertising, testing ..Aug 49
—immediate response ads, tests for ....Aug 47
—information concerning ....Aug 51
—planning ....Aug 45
—repeat ....Aug 49
—results expected ....Aug 45
—using several media ....Aug 50
Credit procedures, proper handling of ....Oct 52
Depreciation reserves for equipment, computing ....Jan 26
Electronic service shop, operating a typical ....Sep 37
Legal services ....Feb 30
—antitrust problems ....Feb 52
—credit problems ....Feb 54
—disposing of business ....Feb 54
—inventory and other financing ....Feb 48
—laws affecting employees ....Feb 50
—litigation ....Feb 54
—organization of business ....Feb 30
—sources of information ....Feb 56

CAPACITORS

Electrolytics in TV ....May 27
—defects and testing ....May 27
—filter defects ....May 32
—picture symptoms ....May 32
—primary filter circuits, in ....May 28
—scoping ....May 32
—secondary circuit applications ....May 29

CITIZENS BAND

Shop, visit to ....Apr 38

COLOR COUNTERMEASURES

Buzz in audio, Philco Chassis 16QT85 ....Feb 58
Color missing or intermittent, RCA Chassis CTC12, 15....Nov 66
Color sync critical, Magnavox Chassis T-918 ....Sep 64
Color sync poor, Sylvania Chassis D01 and D02 ....Oct 62
Color weak, indicator light goes out when color control turned up (Motorola Chassis TS-914) ....Jan 68
Contrast missing, raster and color signals remain on screen (RCA CTC11 chassis) ....Mar 62
....Oct 61
Diathermy interference on high channels, Zenith Chassis 26KC20 Jan 68
Extension cables for Zenith convergence panels, constructing ....Apr 71
Ghosts, evenly spaced, multiple ....Oct 62
Green screen on color, b-w normal (Zenth Chassis 24NC312 and 25NC38) ....Oct 61
Height lost, RCA Chassis CTC24 ....Nov 66
Horizontal and vertical sync intermittent, RCA Chassis CTC22 ....Dec 53
Horizontal bars of color on b-w and color programs, RCA Chassis CTC16, 17 ....Nov 67
Horizontal overscan of blue raster, Zenith Chassis 23XC36, 38 ..Apr 71
Hue changes when color level control is rotated, Zenith Chassis 23XC36, 38 ....Apr 71
Hue control action reversed, Zenith Chassis ....Oct 62
Ringing lines, diagonal (Philco Chassis 16M91) ....Feb 58
Screen temperature shifts to predominate hue after warmup, RCA Chassis CTC22 ....Dec 54
Tinted screen, varies with hue control setting (Magnavox Chassis T-918) ....Sep 64
Vertical jitter, RCA Chassis CTC24 ....Nov 66
Vertical retrace lines, Zenith Chassis 23XC38 ....Feb 58
Width insufficient
—General Electric CB chassis ..Jan 68
—RCA Chassis CTC15 ....Dec 53

COLOR GENERATORS

B & K Model 1242....TE Jun 50
Hickock Model GC660 ....TE May 47
Mercury Model 1900 ....TE Mar 38
RCA Model WR-64B ....Sym Feb 37
—normal operation ....Sym Feb 37
—troubles ....Sym Feb 38
Unijunction transistor employed in multivibrator circuit ..TE May 46

COLOR TV

Bar of color creeps up screen, RCA Chassis CTC15 ....May 23
Blobs of color, sync unstable (Sylvania DO5 Chassis) ....May 55
Blooming, Emerson Chassis 120699 ....VSS Feb 8
Blue and yellow fringing on

horizontal edges of b-w picture ..... Sym Mar 48
Blue and yellow fringing on horizontal edges of b-w picture information ..... Sym Mar 46
Brightness missing, Emerson Chassis 120699 ..... VSS Feb 8
Brightness reduced
—Emerson Chassis 120699 VSS Feb 8
—Motorola Chassis TS-908 ..... VSS May 10
—screen control operation reversed, Motorola Chassis TS-908 ..... VSS May 9
Buzz in audio, Philco Chassis 16QT85 ..... CCM Feb 48
Chroma circuitry, new for 68 ..... Nov 8
Chroma oscillator, operation of ..... Sym Apr 51
Color in b-w program, off-channel snow is confetti ..... Sym Jun 32
Color intermittent, b-w normal
—Admiral Chassis G1263-1 ..... VSS Feb 5
—Olympic Chassis CTC-15/U ..... VSS May 12
Color killer, operation of ..... Sym Jun 31
Color level control must be advanced when switching from strong to weak station .. Sym Jun 34
Color missing
—generator produces 10 green bars ..... Sym Apr 52
—misadjusting color killer produces out-of-sync color ..... Sym Apr 53
—Motorola Chassis TS-912 ..... VSS Jul 13
—or intermittent, RCA Chassis CTC12, 15 ..... CCM Nov 66
—or weak, Motorola Chassis TS-912 ..... VSS Jul 13
—poor vertical sync, Admiral Chassis 25D6 ..... TS Jul 52
Color missing, b-w normal
—Admiral Chassis G1263-1 ..... VSS Feb 6
—indicator light on at all times, Motorola Chassis TS-908 ..... VSS May 10
—Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
—Magnavox Chassis C/U45-01-00 ..... VSS Mar 6
—Olympic Chassis CTC-15/U ..... VSS May 11
—Zenith Chassis, 24MC32, 42 ..... VSS Mar 7
..... Sym Apr 52
..... Sym Jun 32
Color signal, developing the ..... Aug 23
Color sync
—critical, Magnavox Chassis T-918 ..... CCM Sep 64
—intermittent, Magnavox Chassis C/U45-01-00 ..... VSS Mar 6
—intermittent, Zenith Chassis 24MC32, 42 ..... VSS Mar 7
—lost during commercials, Curtis Mathes Chassis CMC15 ..... TS Aug 54
—poor, Sylvania Chassis D01, D02 ..... CCM Oct 62
—troubles ..... Jan 22
—unstable, Truetone Model 2DC/663A ..... VSS Jul 16
Color temperature changes, Sylvania D03 chassis ..... Apr 47
Color weak
—indicator light goes out when color control turned up, Motorola, Chassis TS-914 ..... CCM Jan 68
—on weak stations, sync unstable ..... Sym Apr 54
—or missing, hue control has no effect ..... Sym Jun 33
Colors incorrect due to phase error ..... Sep 32
—symptoms ..... Sep 32
—troubleshooting ..... Sep 33
Contrast lost, raster and color remain (RCA Chassis CTC11) ..... CCM Oct 61
Contrast missing, RCA Chassis CTC11 ..... CCM Mar 62
Convergence assembly ..... Sym Mar 45
CRT troubles ..... Apr 20
Diathermy interference, Zenith Chassis 26KC20 ..... CCM Jan 68
Extension cables for Zenith convergence panels, constructing .. .. CCM Apr 71
Fine tuning control does not function correctly, Motorola Chassis TS-912 ..... VSS Jul 14
Focus poor, brightness low, width reduced (Motorola Chassis TS-908) ..... VSS May 10
Generator signal produces color but phase changes until sync or color is lost ..... Sym Apr 54
Ghosts, evenly spaced, multiple ..... CCM Oct 62
Green flashes on screen, intermittent, (RCA Chassis CTC 12) ..... Apr 22
Green screen on color, b-w normal (Zenith Chassis 24NC312) ..... CCM Oct 61
Green tint on b-w program, disappears after set warms up (Zenith Chassis) ..... Apr 22
Height lost, RCA Chassis CTC24 ..... CCM Nov 66
Horizontal and vertical sync intermittent, RCA Chassis CTC22 ..... CCM Dec 53
Horizontal bars of color on b-w and color programs, RCA Chassis CTC16, 17 ..... CCM Nov 67
Horizontal bars of wrong color drift through color picture, b-w normal ..... Sym Apr 53
Horizontal sync
—drifts, Admiral Chassis G1263-1 ..... VSS Feb 5
—poor or intermittent raster, Motorola Chassis TS-912 ..... VSS Jul 13
—weak, RCA Chassis CTC25X ..... TS Nov 59
Horizontal tear and drift, Truetone Model 2DC1663A ..... VSS Jul 16
Horizontal tearing, vertical roll, Channel 3 beat (RCA Chassis CTC11D) ..... TS Feb 66
Hue changes with rotation of color level control, Zenith Chassis 23XC36, 38 ..... CCM Apr 71
Hue control action reversed, Zenith Chassis ..... CCM Oct 62
Hues unstable, Olympic Chassis CTC-15/U ..... VSS May 12
Killer control inoperative color weak ..... Sym Jun 34
Left side of raster purple, Motorola Chassis TS-908 ..... VSS May 9
Overloaded picture
—Olympic Chassis CTC-15/U ..... VSS May 11
—on strong signal, Motorola Chassis TS-912 ..... VSS Jul 14
Overscan of blue raster, Zenith Chassis 23XC36, 38 ..... CCM Apr 71
Picture missing
—both color and b-w, Zenith Chassis 24MC32, 42 ..... VSS Mar 8
—Truetone Model 2DC1663A ..... VSS Jul 15
Raster black, retrace lines, creeping bar of color (RCA Chassis CTC15 ..... May 23
Red and green vertical lines not converged on left of screen ..... Sym Mar 74
Red color component missing in b-w and color, Admiral Chassis G1263-1 ..... VSS Feb 5
Red excessive in color and b-w picture, Truetone Model 2DC1663A ..... VSS Jul 15
Red vertical fringing on b-w picture information ..... Sym Mar 46
Ringing lines, Philco Chassis 16M91 ..... CCM Feb 58
Ringing on left side of raster, Motorola Chassis TS-912 ..... VSS Jul 14
Screen temperature shifts to predominate hue after warmup, RCA Chassis CTC22 .. CCM Dec 54
Shadows superimposed on picture, increased contrast (RCA Chassis CTC11D) ..... TS Jan 57
Sheet-beam demodulator, operation of ..... Jul 28
68 circuitry ..... Dec 12
—chroma circuitry ..... Nov 8
—CRT control circuits ..... Dec 12
—luminance circuits ..... Dec 16
—models and CRT sizes ..... Nov 6
—sound circuits ..... Dec 23
—sweep and high voltage ..... Dec 20
—tuning and indicator circuits Dec 44
Smeared and out of focus picture, Olympic Chassis CTC-15/U ..... VSS May 12
Solid-state receivers, introduction to Motorola Chassis TS-915 and TS-919 ..... Aug 40
Sound and picture missing, Emerson Chassis 120699 ..... VSS Feb 7
Sweep alignment of color IF amplifiers ..... Nov 41
—double-tuned, two IF system Nov 52
—input and detector pads ..... Nov 44
—stagger-tuned system ..... Nov 50
Tearing and overload of pictures, brightness reduced (Motorola Chassis TS-908) ..... VSS May 9
Tint control inoperative, b-w picture normal (Truetone Model 2DC1663A) ..... VSS Jul 16
Tinted rasters, defects causing ..... Jul 44
Tinted screen, varies with hue control setting (Magnavox Chassis T-918) ..... CCM Sep 64
Tuner AFC defects, symptoms associated with ..... Sym May 42
Vertical and horizontal hold poor, Magnavox Chassis C/U45-01-00 ..... VSS Mar 6
Vertical and horizontal sync missing, Emerson Chassis 120699 ..... VSS Feb 7

Vertical defects ..... Nov 33
—case histories ..... Nov 34
—height insufficient ..... Nov 33
—horizontal white line ..... Nov 33
—intermittent troubles ..... Nov 34
—rolling ..... Nov 34
Vertical drift, Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
Vertical jitter
—Admiral Chassis G1263-1 ..... VSS Feb 6
—RCA Chassis CTC24 CCM Nov 66
Vertical red and green edging over entire screen during b-w program ..... Sym Mar 47
Vertical red lines displaced to right on sides, left in middle ..... Sym Mar 48
Vertical retrace lines, Zenith Chassis 23XC38 ..... CCM Feb 58
Vertical roll, intermittent, (Olympic Chassis CTC-15/U) ..... VSS May 11
Vertical sweep insufficient, bottom compressed (Zenith Chassis 24MC32, 42) .... VSS Mar 8
Vertical sweep missing, Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
Vertical sync poor
—foldover and retrace lines at top, Emerson Chassis 120699 ..... VSS Feb 7
—Zenith Chassis 24MC32, 42 ..... VSS Mar 8
Video amplifier defects, effects on color ..... May 23
Width reduced
—after set operates for extended period, Truetone Model 2DC1663A ..... VSS Jul 15
—General Electric CB chassis ..... CCM Jan 68
—RCA Chassis CTC15 ..CCM Dec 53

COLOR TV SERVICE TRAINING

AGC and sync ..... Sep 51
Bandpass, receiver ..... Sep 46
Chroma circuits ..... Nov 20
—ACC ..... Nov 31
—bandpass amplifier ..... Nov 24
—chroma demodulation ..... Nov 24
—color difference amplifiers .... Nov 28
—color killer ..... Nov 31
—reference oscillator ..... Nov 28
Developing the color signal ..... Aug 23
—chrominance signal ..... Aug 24
—composite color signal ..... Aug 25
—luminance signal ..... Aug 23
—video spectrum ..... Aug 27
Horizontal AFC and oscillator .... Oct 20
Horizontal output and high-voltage circuits ..... Oct 22
Horizontal phase detector ..... Oct 19
Luminance circuits ..... Sep 51
Power supply ..... Sep 54
Sound IF and audio ..... Sep 49
Tuners ..... Sep 46
Vertical deflection circuitry ..... Oct 17
Video IF amplifiers and detector .. Sep 47

CRT TESTERS

B & K Model 465 ..... TE Jul 49
Hickock Model CR 35 ..... TE Sep 58
SENCORE Model CR 13 ..... TE Dec 40
SENCORE Model CR 143 ..... TE Aug 52

DIODES

Forward and reverse resistances, measurement of ..... Sep 13

FILMENT CIRCUITS

Thermistors, application of ..... Jul 30

FM RADIO

FM reception noisy, AM and phono normal, (RCA Chassis RC-1227B) ..... Oct 34
Color coding of oscillator and IF transformer adjustments .. TS Apr 65
Hissing sound on FM, AM normal (Truetone Model 4DC-5665A) ..... Oct 32
Troubleshooting methods ..... Jun 40
—case histories ..... Jun 44
—noise generators ..... Jun 40
—signal generators ..... Jun 40
—transistor checking ..... Jun 41

GUIDES

Source guide to imports ..... Feb 28
TV Tube Stock Guide ..... Apr 24

HIGH VOLTAGE

Color TV, circuitry employed in .. Oct 22
Missing, along with boost and raster (Zenith Chassis 14M20) .. TS Oct 48
Solid-state
—operational analysis ..... Sep 9
—symptom analysis ..... Sep 12
—troubleshooting procedure .... Sep 11

HORIZONTAL OUTPUT TRANSFORMERS

Arcing from secondary to iron core ..... TS Mar 60
Overheating, Zenith Chassis 16E25 ..... TS Jun 56

HORIZONTAL SWEEP

Circuit action, sequence of ..... Sep 11
Flyback overheating, Zenith Chassis 16E25 ..... TS Jun 56
Horizontal output tube overheats, Admiral Chassis 1601 ..... TS Feb 66
Output circuit employed in color receivers ..... Oct 22
Solid-state
—operational analysis ..... Sep 9
—symptom analysis ..... Sep 12
—troubleshooting procedure .... Sep 11
Transistor TV, employed in ..... Jun 39
Reduced
—brightness low, focus poor (Motorola Chassis TS-908) ..... VSS May 10
—General Electric CB Chassis ..... CCM Jan 68
—RCA Chassis CTC15 ..CCM Dec 53
—solid-state circiutry, in ..... Sep 14
—Truetone Model 2DC1663A ..... VSS Jul 15

HORIZONTAL SYNC

Color TV, circuits employed in .... Oct 19
Drift, Admiral Chassis G1263-1 ..... VSS Feb 5
Poor, or intermittent raster (Motorola Chassis TS-912) ..... VSS Jul 13
Quivers, Westinghouse Chassis V-2233-4 ..... Jan 17
Servicing, general information ..... Jul 42
Solid-state circuitry ..... Aug 11
—common troubles ..... Aug 12
—DC voltage distribution ..... Aug 11
Sync coupling, analysis of ..... Jul 40
Tear and drift, Truetone Model 2DC1663A ..... VSS Jul 16
Tearout caused by defective filter Jan 18
Twist, post-video (Trav-ler Chassis 740-78) ..... TS Aug 54
Unstable ..... Sep 16
Weak, RCA Chassis CTC25X TS Nov 59

HUM

Until raster appears, Zenith Chassis 15L22 ..... TS May 58

IF SECTION OF TV

Troubleshooting with oscilloscope Apr 4
—ground circuit difficulties ..... Apr 6
—hum in IF signal ..... Apr 5
—low contrast versus stage gain Apr 5
—picture pulling or loss of sync Apr 5
—poor picture quality ..... Apr 4

INDUSTRIAL ELECTRONICS

Basic circuits ..... Jan 45
—anti-chatter relay ..... Jan 45
—dual primary transformer ..... Jan 45
—load positioning control ..... Jan 48
—manual/automatic control circuits ..... Jan 45
—modulated-light photorelay .... Jan 46
—self-latching relay ..... Jan 50
—shockover capacitor ..... Jan 46
—thermocouple break protection ..... Jan 49
—voltage regulation ..... Jan 46
Circuit descriptions and functions Apr 28
—bin-level control ..... Apr 32
—chopper amplifier ..... Apr 36
—conductivity meter ..... Apr 32
—differential transformer ..... Apr 28
—energy-storage welding ..... Apr 30
—flame-failure safeguard ..... Apr 33
—infrared pyrometer ..... Apr 36
—*nixie* readout ..... Apr 32
—phase-controlled rectifier ..... Apr 28
—photomultiplier ..... Apr 56
—saturable reactor ..... Apr 30
—ultrasonic sensor ..... Apr 33

INTERFERENCE

Diathermy on higher channels, Zenith Chassis 26KC20 ..... CCM Jan 68
TVI traps, setting ..... TS Jun 56

INTERMITTENT TROUBLES

Collapsed raster, Admiral Chassis G13 ..... Nov 35
Color intermittent, b-w normal
—Admiral Chassis G1263-1 ..... VSS Feb 5
—Olympic Chassis CTC-15/U ..... VSS May 12
Color, RCA Chassis CTC12, 15 ..... CCM Nov 66
Color sync
—Magnavox Chassis C/U45-01-00 ..... VSS Mar 6
—Zenith Chassis 24MC32, 42 ..... VSS Mar 7
Green flashes on screen, RCA Chassis CTC12 ..... Apr 22
Height, Admiral Chassis D11 ..... Nov 37
Horizontal and vertical sync, RCA Chassis CTC22 ..... CCM Dec 53
Horizontal quiver, Westinghouse Chassis V-2233-4 ..... Jan 17

Raster intermittent or poor horizontal sync, Motorola Chassis TS-912 ....VSS Jul 13
Reduced raster, RCA Chassis CTC19 ....Nov 34
Vertical roll
—caused by video signal distortion ....Jan 20
—Crosley Model 487 ....Jan 19
—Olympic Chassis CTC 15/U ....VSS May 11
—Philco Chassis 17MT80 ....Nov 37
Vertical sweep, Admiral Chassis 21B1 ....TS May 58
Vertical sync, RCA Chassis KCS68 ....Jan 18
Volume weak on right channel, RCA Model VGP82 ....Jun 47

MISCELLANEOUS

Adapting extension cable to fit octal plug ....May 39
Electronic cables ....Feb 19
—characteristics ....Feb 19
—handling techniques ....Feb 21
—high fidelity ....Feb 23
—installation techniques ....Feb 22
—television lead-in ....Feb 24
Organ servicing, getting started in ....May 25
Symbol standardization ....Jan 1

NOTES ON TEST EQUIPMENT

Amphenol Model 870 FET Voltmeter ....Oct 28
B & K Model 465 CRT Tester ....Jul 49
B & K Model 1242 Color Generator ....Jun 50
Hickock Model CR 35 CRT Tester ....Sep 58
Hickock Model GC 660 Color Generator ....May 47
Hickock Model 860 Injecto-Tracer ....Aug 52
Lectrotech Model TT-250 Transistor Anaylzer ....Nov 39
Mercury Model 1900 Color Generator ....Mar 38
Precision Model E-200-C RF Generator ....Feb 34
Seco Model HC8 In-Circuit Current Checker ....Nov 40
Seco Model 107-C Tube Tester ....Jul 50
Semitron Model 1000 Transistor Tester and Set Analyzer ....Mar 39
SENCORE Model CR13 CRT Tester/ Rejuvenator ....Dec 40
SENCORE Model CR 143 CRT Tester ....Aug 52
SENCORE Model MP-140 Tube Tester ....Apr 44
Triplett Model 600 FET Meter ....Dec 44
Unijunction transistor multivibrator used in color generators ....May 46

OSCILLOSCOPES

Advantages and limitations of ....Jun 28
IF section, using to signal trace in ....Apr 4
Probes used with ....Mar 28
—applications ....Mar 59
—capacitance divider ....Mar 56
—combination isolating and direct ....Mar 30
—demodulator probe ....Mar 44
—direct probe ....Mar 28
—low-capacitance probes ....Mar 42
TV tuner, using to troubleshoot ....Apr 1
Video amplifier, using to signal trace in ....Apr 7

PICTURE SYMPTOMS

Barkhausen line ....Sep 16
Blobs of color on screen, sync unstable (Sylvania Chassis DO5) ....May 55
Blue and yellow fringing on horizontal edges of b-w picture information ....Sym Mar 46
.... Sym Mar 48
Brightness missing, Emerson Chassis 120699 ....VSS Feb 8
Brightness reduced
—Emerson Chassis 120699 VSS Feb 8
—Motorola Chassis TS-908 ....VSS May 10
—screen control operation reversed, Motorola Chassis TS-908 ....VSS May 9
Color bar creeps up screen, no color on rest of screen (RCA Chassis CTC15) ....May 23
Color in b-w program, off-channel snow is confetti ....Sym Jun 32
Color intermittent, b-w normal
—Admiral Chassis G1263-1 ....VSS Feb 5
—Olympic Chassis CTC-15/U ....VSS May 12
Color missing
—misadjusting color killer produces out of sync color ....Sym Apr 53
—Motorola Chassis TS-912 ....VSS Jul 13
—on station signal, generator produces 10 green bars ..Sym Apr 52
—or intermittent, RCA Chassis CTC12, 15....CCM Nov 66
—or weak, Motorola Chassis TS-912 ....VSS Jul 13
—poor vertical sync, Admiral Chassis 25D6 ....TS Jul 52
Color missing, b-w normal
—Admiral Chassis G1263-1 ....VSS Feb 6
—indicator light on at all times, Motorola Chassis TS-908 ....VSS May 10
—Magnavox Chassis C/U45-01-00 ....VSS Mar 5
—Magnavox Chassis C/U45-01-00 ....VSS Mar 6
—Olympic Chassis CTC-15/U ....VSS May 11
—Zenith Chassis 24MC32, 42 ....VSS Mar 7
.... Sym Apr 52
.... Sym Jun 32
Color overloads when switching from weak to strong station ....SYM Jun 34
Color sync
—critical, Magnavox Chassis T-918 ....CCM Sep 64
—intermittent, Magnavox Chassis C/U45-01-00 ....VSS Mar 6
—intermittent, Zenith Chassis 24MC32, 42 ....VSS Mar 7
—lost during commercials, Curtis Mathes Chassis CMC15 ....TS Aug 54
—poor, Sylvania Chassis D01 and D02 ....CCM Oct 62
—unstable, Truetone Model 2DC1663A ....VSS Jul 16
Color temperature shifts, Sylvania D03 chassis ....Apr 47
Color weak, killer control inoperative ....Sym Jun 34
Color weak, Motorola Chassis TS914 ....CCM Jan 68
Color weak on weak stations, sync unstable ....Sym Apr 54
Color weak or missing, hue control has no effect ....Sym Jun 33
Colors incorrect, b-w normal ....Sep 32
Contrast lost
—raster and color remain, RCA Chassis CTC11 ....CCM Oct 61
—RCA Chassis CTC11 ..CCM Mar 62
Contrast low ....Apr 5
Definition poor, caused by defect in video amplifier ....Apr 8
Electrolytic capacitor failures, caused by ....May 30
Focus lost when antenna disconnected or brightness control adjusted from 3/4 to maximum, Admiral Chassis 1G1155-1 ....TS Aug 55
Focus poor, brightness low, width reduced (Motorola Chassis TS-908) ....VSS May 10
Ghosts, evenly spaced, multiple ....CCM Oct 62
Green flashes on screen, intermittent, (RCA Chassis CTC12) ....Apr 22
Green screen on color, b-w normal (Zenith Chassis 24NC31,Z) ....CCM Oct 61
Green tint on b-w program disappears after set warms up (Zenith Chassis) ....Apr 22
Horizontal bars of color on b-w and color programs, RCA Chassis, CTC16, 17 ....CCM Nov 67
Horizontal bars of wrong color drift through color picture, b-w normal ....Sym Apr 53
Hue changes with rotation of color level control, Zenith Chassis 23XC36, 38 ....CCM Apr 71
Hue control action reversed, Zenith Chassis ....CCM Oct 62
Hue unstable, Olympic Chassis CTC-15/U ....VSS May 12
Hum bar ....Apr 5
Left side of raster purple, Motorola Chassis TS-908 ....VSS May 9
Muddy and filled up, caused by defect in video amplifier ....Apr 7
Overload on strong signal, Motorola Chassis TS-912 ....VSS Jul 14
Overloaded picture, Olympic Chassis CTC-15/U ....VSS May 11
Picture and sound missing, Emerson Chassis 120699 ....VSS Feb 7
Picture missing
—both b-w and color, Zenith Chassis 24MC32, 42 ....VSS Mar 8
—Truetone Model 2DC1663A ....VSS Jul 15
Poor picture quality ....Apr 4
Ringing and circuit ghosts caused by defects in video amplifier ..Apr 8
Red and green vertical lines not converged on left of screen ....Sym Mar 47
Red color component missing in

b-w and color, Admiral Chassis G1263-1 ..... VSS Feb 5
Red excessive in color and b-w picture, Truetone Model 2DC1663A ..... VSS Jul 15
Red vertical fringing on b-w picture information ..... Sym Mar 46
Ringing caused by IF regeneration ..... Apr 4
Screen temperature shifts to predominate hue after warmup, RCA Chassis CTC22 .... CCM Dec 54
Shadows filter across screen, increased contrast (RCA Chassis CTC11D) ..... TS Jan 57
Single 2" bar of color, rest of screen black (RCA Chassis CTC 15) ..... May 23
Smeared and out of focus, Olympic Chassis CTC-15/U ..... VSS May 12
Sweep alignment, indicating need for ..... June 5
Tearing and overload, brightness reduced (Motorola Chassis TS-908) ..... VSS May 9
Tinted screen, varies with hue control setting (Magnavox Chassis T-918) ..... CCM Sep 64
Trap off frequency in video IF, effect of ..... Jun 10
Tuner AFC defects, associated with ..... Sym May 42
Twist and bends caused by electrolytic filter defects ..... May 30
Twist, post video (Trav-ler Chassis 740-78) ..... TS Aug 54
Vertical red and green edging over entire screen during b-w program ..... Sym Mar 47
Vertical red lines displaced to right on sides, left in middle ..... Sym Mar 48
Video and audio disappear, Philco Chassis 14N50 ..... TS Dec 55
Video missing, sound poor (General Electric Chassis AY) ..... TS May 57
Video overload on strong signals, Admiral Chassis G1263-1 ..... VSS Feb 6
Weak reception on all channels, heavy snow, distorted sound (Motorola Chassis TS-408A) ..... TS Apr 63

PICTURE TUBES

Arcing at anode connection, Olympic Model 6P25 ..... TS Apr 65
Defects, pinpointing ..... Apr 20
Filament burned open, Motorola Chassis 534D-13 ..... TS May 59
Green tint on b-w program disappears after set warms up (Zenith Chassis) ..... Apr 22
Heater to cathode short causes loss of contrast, RCA Chassis CTC11 ..... CCM Mar 62
Impurities, permanent ..... Apr 22
Intermittent green flashes on screen caused by bad CRT, RCA CTC12 chassis ..... Apr 22
Spot elimination circuit employed in Admiral H5 chassis ..... Oct 6
Substitution, RCA Chassis 72A ..... TS Apr 63

POWER SUPPLIES

Color receivers, used in ..... Sep 54
Electrolytic capacitor applications ..... May 28
Twists and bends, defects causing May 31

PREVIEWS OF NEW SETS

Admiral Model LKS6511M, Chassis 1H1298-2 ..... Mar 1
Airline Model GHJ7537B, Chassis 913-179466 ..... May 5
Emerson Model 23T02, Chassis 120844A ..... Mar 2
General Electric Model M980CWD, Chassis KC ..... May 6
Magnavox Model 30U505K, Chassis V918-01-BB ..... Feb 1
Motorola Model CTC606CN, Chassis 20TS-918A-00 ..... Feb 2
Motorola Model XP201CU, Chassis 9TS-460A-09 ..... Jul 9
Packard Bell Model CSW-606, Chassis 98C15 ..... Mar 3
Philco-Ford Model 85506SEA, Chassis 17MT80B ..... Mar 4
Pilot Model C309 ..... May 7
RCA Model AJ-00E, Chassis KCS157A ..... Jul 10
RCA Model GH784H, Chassis CTC21C ..... Feb 3
Sears Model 7160, Chassis 562.10220 ..... Jul 11
Sylvania Model 19TC14-1, Chassis D05-1 ..... May 8
Zenith Model X4541W, Chassis 20X1C36 ..... Jul 12
Zenith Model 25X6547M, Chassis 23XC36 ..... Feb 4

RADIO

Sound reduced on lower frequencies, General Electric Model C403G ..... TS Feb 66

RASTER (FAULTS)

Barkhausen lines ..... Sep 16
Black raster, retrace lines, small creeping bar of color (RCA Chassis CTC15) ..... May 23
Blooming
—causes of in solid-state circuits ..... Sep 15
—Emerson Chassis 120699 .. VSS Feb 8
Boost, high voltage, and raster missing (Zenith Chassis 14M20) ..... TS Oct 48
Brightness reduced
—Motorola Chassis TS-908 ..... VSS May 10
—screen control operation reversed, Motorola Chassis TS-908 ..... VSS May 9
—tearing and overload, Motorola Chassis TS-908 ..... VSS May 9
Collapsed raster, Admiral Chassis G13 ..... Nov 35
Delayed height, Motorola Chassis WKTS-584 ..... TS Jan 59
Foldover, vertical (Sylvania Chassis D03) ..... Nov 36
Height insufficient, Motorola Chassis TS-586/Y ..... TS Dec 57
Height intermittent, Admiral Chassis D11 ..... Nov 37
Height reduced, RCA Chassis CTC16XL ..... Nov 34
Horizontal foldover, causes of in solid-state circuits ..... Sep 15
Horizontal nonlinearity, causes of in solid-state circuits ..... Sep 16
Horizontal sync drifts, Admiral Chassis G1263-1 ..... VSS Feb 5
Horizontal sync unstable ..... Sep 16
Intermittent raster or poor horizontal sync, Motorola Chassis TS-912 ..... VSS Jul 13
Intermittent reduced raster, RCA Chassis CTC19 ..... Nov 34
Jitter and bounce, RCA Chassis CTC15 ..... Nov 37
Keystoning ..... Sep 16
Overscan of blue raster, Zenith Chassis 23XC36, 38 ..... CCM Apr 71
Purple tint on left of raster, Motorola Chassis TS-908 ..... VSS May 9
Missing
—causes of in solid-state circuits ..... Sep 12
—sound normal, General Electric MW chassis ..... TS Feb 65
Reduced
—at top, RCA Chassis KCS151 ..... Mar 75
—Motorola Chassis TS-912 .... Nov 36
—top only, RCA Chassis CTC20A ..... Nov 38
Ringing lines, Philco Chassis 16M91 ..... CCM Feb 58
Ringing on left side of raster, Motorola Chassis TS-912 ..... VSS Jul 14
Tinted raster, defects that cause .... Jul 44
Vertical drift, Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
Vertical jitter, Admiral Chassis G1263-1 ..... VSS Feb 6
Vertical retrace lines, Zenith Chassis 23XC38 ..... CCM Feb 58
Vertical roll
—caused by defective VDR, Admiral Chassis 25H6 ..... Nov 38
—intermittent, Olympic Chassis CTC-15/U ..... VSS May 11
—intermittent, Philco Chassis 17MT80 ..... Nov 37
—RCA Chassis CTC20 ..... Nov 38
Vertical sweep
—insufficient, bottom compressed (Zenith Chassis 24MC32, 42) ..... VSS Mar 8
—intermittent, Admiral Chassis 21B1 ..... TS May 58
—missing, Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
Width reduced
—brightness low, focus poor (Motorola Chassis TS-908) ..... VSS May 10
—causes of in solid-state circuits ..... Sep 14
—RCA Chassis CTC15 .. CCM Dec 53
—Truetone Model 2DC1663A ..... VSS Jul 15
Yoke ringing ..... Sep 16

RESISTORS

Thermistors ..... Jul 30
—deflection circuits, in ..... Jul 31
—filament strings, in ..... Jul 30
—servicing ..... Jul 32
—typical resistance ..... Jul 30
Varistors ..... Jul 32
—deflection circuits, in ..... Jul 34
—servicing ..... Jul 34
—voltage/resistance, typical ..... Jul 34

SIGNAL GENERATORS, RF

Precision Model E-200-C ..... TE Feb 34

RCA Model WR-50B .....Jan 39

SOUND SECTION OF TV

Alignment, symptoms indicating need for .....Jun 6
Buzz, Philco Chassis 16QT85 .....CCM Feb 58
Color receivers, used in .....Sep 49
Distortion, heavy snow on screen (Motorola Chassis TS-408A) .....TS Apr 63
Electrolytic capacitor applications .....May 29
Grid leakage in output tube, de Forest Model DKW .....TS Sep 68
Hum until raster appears, Zenith Chassis 15L22 .....TS May 58
Integrated circuit, sound system employing .....Oct 8

STEREO FM

Audio weak on stereo and monaural, no separation on stereo ..Sym Jan 43
Audio weak on stereo and monaural, separation poor, but indicator lights .....Sym Jan 44
Audio weak on stereo and monaural, stereo indicator illuminated .....Sym Jan 43
Distortion and weak, garbled volume in left channel (Electrohome Model TR30M) .....Oct 37
Distortion in right channel, Magnavox Chassis R204-10 .....Oct 36
FM and AM reception missing, phono normal (RCA Chassis RC1223A) .....Oct 33
FM reception noisy, AM and phono normal (RCA Chassis RC-1227B) .....Oct 34
FM reception poor, rushing sound in speaker (Admiral 20C4A chassis) .....Jun 47
High-quality systems, servicing ....Aug 32
—components .....Aug 32
—distortion measurement .....Aug 38
—frequency response .....Aug 58
—sensitivity measurement .....Aug 38
—separation measurement .....Aug 58
—system analysis .....Aug 33
—tuner bandpass measurement .....Aug 38
—turntable tests .....Aug 60
Hissing sound on FM, AM normal (Truetone Model 4DC-5665A) .....Oct 32
Left channel intermittent on radio and phono positions, General Electric Chassis .....Jun 44
Motorboating in left channel, RCA Chassis .....Jun 47
Noise during stereo reception, separation poor .....Sym Jan 44
No stereo reception, Silvertone Chassis 528.63310 .....Oct 34
Separation missing on stereo FM .....Sym Jan 42
Separation poor on strong signal, missing on weak .....Sym Jan 42
Troubleshooting procedures
—audio stages .....Oct 36
—circuit analysis .....Oct 32
—multiplex stages, in .....Oct 34
—noise generators, with .....Jun 40
—signal generators, with .....Jun 40
—signal injection .....Oct 33
—transistor checking .....Jun 41
—VTVM or VOM tests .....Oct 33
Volume intermittently weak on right channel, RCA Model VGP82 Jun 47
Volume low on right channel, RCA Model VFP 32E .....Jun 44
Warm up slow, Silvertone Chassis 528.63430 .....Jun 48

SYMFACT

Chroma oscillator .....Apr 51
Color Generator, RCA Model WR-64B .....Feb 37
Color killer .....Jun 31
Convergence Assembly .....Mar 45
Multiplex amplifier and doubler ..Jan 41
Tuner AFC, RCA Chassis CTC21C .....May 41

SYNC (Also see horizontal and vertical)

Analysis of .....Jul 35
—horizontal sync coupling .....Jul 40
—servicing procedures .....Jul 42
—sync separator .....Jul 35
—vertical sync coupling .....Jul 35
Color receiver, circuitry in .....Sep 51
Horizontal and vertical intermittent, RCA Chassis CTC22 .....CCM Dec 53
Horizontal tearing, vertical roll, Channel 3 beat (RCA Chassis CTC11D) .....TS Feb 66
Intermittent and time-lapse troubles .....Jan 17
Solid-state circuitry .....Aug 7
—horizontal AFC and oscillator .....Aug 11
—vertical sweep .....Aug 7
Vertical and horizontal hold poor .....VSS Mar 6
Vertical and horizontal sync missing, Emerson Chassis 120699 .....VSS Feb 7

TELEVISION

AGC, keyed .....Dec 30
Color models for 68 .....Nov 6
Electrolytic capacitors used in ....May 27
Lead-in .....Feb 24
—coaxial type .....Feb 26
—installation tips .....Feb 60
—losses .....Feb 24
—shielded twin-lead .....Feb 60
1968 TV lines, models and features of .....Oct 4
Station test signal .....TS Feb 66
Sweep alignment .....Jun 5
—difficulties and precautions ....Jun 8
—misaligned traps, effects of .....Jun 9
—peak alignment .....Jun 11
—response curves, interpreting ..Jun 6
—RF-IF response, checking ....Jun 10
—step-sweep IF alignment .....Jun 11
—symptoms indicating need for..June 5
—traps, aligning .....Jun 10
Transistor, servicing .....Jun 36

TEST EQUIPMENT

CRT Testers
—B & K Model 465 .....TE Jul 49
—Hickok Model CR 35 .....TE Sep 58
—SENCORE Model CR 13 ....TE Dec 40
—SENCORE Model CR 143 ..TE Aug 52
Color generators
—B & K Model 1242 .....TE Jun 50
—Hickok Model GC 660 ..TE May 47
—Mercury Model 1900 .....TE Mar 38
—RCA Model WR-64B ....Sym Feb 37
Electronic Organs, for repairing ..May 52
FET Voltmeters
—Amphenol Model 870 .....TE Oct 28
—Triplett Model 600 .....TE Dec 41
In-circuit current checker, Seco Model HC8 .....TE Nov 40
Meters (VTVM and VOM)
—application of .....Jun 25
—frequency response .....Jun 26
—input capacitance .....Jun 26
—waveform errors .....Jun 28
Ohms and AC functions defective, Olson TE-168 VOM .....TS Mar 60
Oscilloscopes, advantages and limitations of .....Jun 28
RF signal generators
—Precision Model E-200-C..TE Feb 34
—RCA Model WR-50B .....Jan 39
Scope or meter, deciding which .....Jun 25
Signal tracer, Hickok Model 860 Injector-Tracer .....TE Aug 52
Transistor analyzer, Lectrotech Model TT-250 .....TE Nov 39
Transistor Tester and Set analyzer, Semitron Model 1000 ....TE Mar 39
Tube testers
—Mercury Model 2000 .....Jan 38
—Seco Model 107-C .....TE Jul 50
—SENCORE Model MP-140 ..TE Apr 44

THEORY

Color signal, development of .....Aug 23
Field effect transistors .....Sep 34
Ohm's law for AC .....Jan 28
Organs .....May 26
RC Circuits .....Oct 38
Sheet-beam demodulator .....Jul 28
Symbol standardization .....Jan 1
Sync, horizontal and vertical .....Jul 35

TRANSISTORS

Beta and leakage readings in AM-FM chassis .....Oct 33
DC voltage distribution .....Dec 4
—bias circuits .....Dec 56
—collector junction leakage .....Dec 4
—common base circuits .....Dec 6
—common collector circuits ....Dec 56
—cutoff test .....Dec 5
—open and shorted collector junctions .....Dec 5
—voltage indications, comparative .....Dec 6
FET used in voltmeter .....TE Oct 28
Field effect transistors, introduction to .....Sep 34
—basic theory .....Sep 34
—features of .....Sep 34
—precautions .....Sep 44
—test procedures .....Sep 36
Replacement table for AM-FM chassis .....Oct 32
Testing .....Jun 41
—beta .....Mar 25
—characteristics .....Jun 41
—in-circuit .....Jun 37
—leakage .....Mar 25
—symptom association .....Jun 43
Testers, typical .....Mar 26
Unijunction transistor employed in vertical oscillator .....Oct 7
Unijunction transistor multivibrator used in color generators .....TE May 46
Lectrotech Model TT-250 .....TE Nov 39

TRANSISTOR TESTERS

Operation of .....Mar 24
—beta tests .....Mar 25
—leakage tests .....Mar 25

—typical instruments ..... Mar 26
Semitron Model 1000 ..... TE Mar 39
Solid-state stereo, using to check transistors in ..... Jun 41

TRANSISTOR TV

Deflection circuits
—horizontal AFC and oscillator ..... Aug 11
—horizontal output and high voltage ..... Sep 9
—horizontal troubles ..... Aug 12
—vertical sweep ..... Aug 7
—vertical troubles ..... Aug 9
Motorola all-transistor Chassis TS-915 and TS-919, introduction to ..... Aug 40
Troubleshooting techniques ..... Jun 36
—AGC circuits ..... Jun 62
—basics ..... Jun 36
—horizontal circuits ..... Jun 39
—in-circuit testing ..... Jun 37
—precautions ..... Jun 64
—special circuits ..... Jun 38
—vertical circuits ..... Jun 62

TROUBLESHOOTER, THE

Arcing at CRT anode connection, Olympic Model 6P25 ..... Apr 65
Arcing from "S" winding of flyback to iron core ..... Mar 60
CRT filament burnout, repeated (Motorola Chassis 534D-13) ..... May 59
CRT substitution, RCA Chassis 72A ..... Apr 63
Color coding of oscillator and IF transformer adjustments in AM/FM radios ..... Apr 65
Color missing, poor vertical sync (Admiral Chassis 25D6) ..... Jul 52
Color sync lost during commercials, Curtis Mathes Chassis CMC15 ..... Aug 54
Delayed height, Motorola Chassis WKTS-584 ..... TS Jan 59
Focus lost when antenna disconnected or brightness control adjusted from ¾ to maximum, Admiral Chassis 1G1155-1 ..... Aug 55
Grid leakage in audio output tube, de Forest Model DKW ..... Sep 68
Heavy snow on screen, distorted sound (Motorola Chassis TS-408A) ..... Apr 63
Height insufficient, Motorola Chassis TS-586/Y ..... Dec 57
High end of band inoperative when receiver installed in car, Pontiac Model 983873 ..... Jun 56
Horizontal output transformer overheating, Zenith Chassis 16E25 ..... Jun 56
Horizontal output tube overheats, Admiral Chassis 1601 ..... Feb 66
Horizontal sync weak, RCA Chassis CTC25X ..... Nov 59
Horizontal tearing, vertical roll, Channel 3 beat (RCA Chassis CTC11D) ..... Feb 66
Hot cabinet, Zenith Model Z1511-BUZ ..... Nov 59
Hum until raster appears, Zenith Chassis 15L22 ..... May 58
Ohms and AC functions defective, Olson TE-168 VOM ..... Mar 60
Raster, boost, and high voltage missing (Zenith Chassis 14M20) ..... Oct 48
Raster missing, sound normal (General Electric Chassis MW) ..... Feb 65
Shadows and increased contrast, RCA Chassis CTC11D ....TS Jan 57
Sound reduced on lower frequencies, General Electric Model C403G radio ..... Feb 66
Station test signal ..... Feb 66
TVI traps, setting ..... Jun 56
Twist, post video (Trav-ler Chassis 740-78) ..... Aug 54
Vertical roll after one hour of operation, Zenith Chassis 14L20 ..... Oct 47
Vertical sweep intermittent, Admiral Chassis 21B1 ..... May 58
Vertical sync poor, Zenith Chassis 14M21/X ..... Oct 45
Vertical sync weak
—Sears Model 9146B ..... Nov 60
—Zenith Chassis 14N33 ..... Nov 60
Video and audio disappear, Philco Chassis 14N50 ..... Dec 55
Video and sound disappear when contrast control is turned down, Admiral Chassis 20B6CB ..... Sep 68
Video missing, sound poor (General Electric Chassis AY) ..... May 57
Wavy pattern when tuning near sound side, Setchell Carlson receivers ..... Oct 47

TUBES

Heater to cathode shorts, effects on raster and color ..... May 24
Sheet-beam chroma demodulator ..... Jul 28
Stock Guide for TV ..... Apr 24
Substitution of 6GM6 for 6AU6 cures trouble ..... TS Jul 52

TUBE TESTERS

Mercury Model 2000 ..... Jan 38
Seco Model 107-C ..... TE Jul 50
SENCORE Model MP-140 ..... TE Apr 44

TUNERS, TV

Automatic frequency control, operation of ..... Sym May 41
Balun coil, rewinding ..... Jan 24
Color receivers, used in ..... Sep 46
Fine tuning control does not function correctly, Motorola Chassis TS-912 ..... VSS Jul 14
Troubleshooting with oscilloscope ..... Apr 1

VERTICAL SWEEP

Collapsed raster, intermittent (Admiral Chassis G13) ..... Nov 35
Color TV, circuits employed in ..Oct 17
Delayed height, Motorola Chassis WKTS-584 ..... TS Jan 59
Foldover, Sylvania Chassis D03 ..Nov 36
Intermittent
—Admiral Chassis D11 ..... Nov 37
—Admiral Chassis 21B1 ....TS May 58
Jitter, Admiral Chassis G1263-1 ..... VSS Feb 6
Missing
—Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
—RCA Chassis CTC24 ..CCM Nov 66
Reduced
—bottom compressed, Zenith Chassis 24MC32, 42 ..... VSS Mar 8
—intermittent, RCA Chassis CTC19 ..... Nov 34
—Motorola Chassis TS-586/Y ..... TS Dec 57
—Motorola Chassis TS-912 ....Nov 36
—RCA Chassis CTC16XL ..... Nov 34
Retrace lines, Zenith Chassis 23XC38 ..... CCM Feb 58
Solid-state circuitry ..... Aug 7
—common troubles ..... Aug 9
—output stage ..... Aug 8
—sawtooth generation ..... Aug 7
—two-stage system ..... Aug 8
Top reduced, RCA Chassis CTC20A ..... Nov 38
Transistor TV, employed in ..... Jun 62
Unijunction transistor employed in oscillator, Electrohome M5 Chassis ..... Oct 7
Vertical pulse contaminating horizontal sweep, RCA Chassis KCS151 ..... Mar 75

VERTICAL SYNC

Drift, Magnavox Chassis C/U45-01-00 ..... VSS Mar 5
Instability resulting from difference in b-w and color vertical frequency ..... Jan 21
Intermittent with jitter, RCA Chassis KCS68 ..... Jan 18
Jitter
—RCA Chassis CTC15 ..... Nov 37
—RCA Chassis CTC24 ..CCM Nov 66
Poor
—color missing, Admiral Chassis 25D6 ..... TS Jul 52
—foldover and retrace lines at top, Emerson Chassis 120699 ..... VSS Feb 7
—Zenith Chassis 14M21/X ..... TS Oct 45
—Zenith Chassis 24MC32, 42 ..... VSS Mar 8

Roll
—after one hour of operation, Zenith chassis 14L20 ..... TS Oct 47
—caused by defective VDR, Admiral Chassis 25H6 ..... Nov 38
—intermittent, caused by video signal distortion ..... Jan 20
—intermittent, Crosley Model 487 ..... Jan 19
—intermittent, Olympic Chassis CTC-15/U ..... VSS May 11
—intermittent, Philco Chassis 17MT80 ..... Nov 37
—RCA Chassis CTC20 ..... Nov 38
—slow, Sylvania Chassis D02 ..Nov 35
Servicing procedures ..... Jul 42
Sync coupling, analysis of ..... Jul 35
Weak
—Sears Model 9156B ..... TS Nov 60
—Zenith Chassis 14N33 ....TS Nov 60

VIDEO

Amplifier defects, effects on color ..... May 23
Amplifier, signal tracing in ..... Apr 7
Color missing, b-w pix normal (Magnavox Chassis C/U45-01-00) ..... VSS Mar 5
Color receiver, circuitry used in....Sep 47
Contrast low ..... Apr 5
Definition poor ..... Apr 8
Delay line causes loss of brightness, Emerson

Chassis 120699 .....VSS Feb 8
Disappears along with audio, Philco Chassis 14N50 .....TS Dec 55
Hum in IF signal .....Apr 5
IF amplifiers, sweep alignment of .....Jun 5
Overload
—Olympic Chassis CTC-15/U .....VSS May 11
—on strong signals, Admiral Chassis G1263-1 .....VSS Feb 6
Picture and sound missing, Emerson Chassis 120699 VSS Feb 7
Picture missing
—both b-w and color, Zenith Chassis 24MC32, 42 .....VSS Mar 8
—sound poor, General Electric AY chassis .....TS May 57
—Truetone Model 2DC1663A .....VSS Jul 15
Picture pulling or loss of sync .....Apr 5
Poor picture quality .....Apr 4
Ringing and circuit ghosts .....Apr 8
Smeared and out of focus picture, Olympic Chassis CTC-15/U .....VSS May 12
Twist, post video (Trav-ler Chassis 740-78) .....TS Aug 54
Video and sound disappear when contrast control is turned down, Admiral Chassis 20B6CB .....TS Sep 68
White compression .....Apr 7

VIDEO SPEED SERVICING

Admiral Chassis G1263-1 .....Feb 5
Emerson Chassis 120699 .....Feb 7
Olympic Chassis CTC-15/U .....May 11
Magnavox Chassis C/U45-01-00 ..Mar 5
Motorola Chassis TS-908/A,B,YA,YB .....May 9
Motorola Chassis TS-912 .....Jul 13
Truetone Model 2DC1663A, 65A, 67A .....Jul 15
Zenith Chassis 24MC32, Z and 24MC42, Z .....Mar 7

VOM's

Application of .....Jun 25
FET type, Amphenol Model 870 .....TE Oct 28
Frequency response .....Jun 26
Input capacitance .....Jun 26
Ohms and AC functions defective, Olson TE-168 VOM .....TS Mar 60
Transistorized, Triplett Model 600 .....TE Dec 41
Waveform errors associated with .....Jun 28

VTVM's

Application of .....Jun 25
FET type, Amphenol Model 870 .....TE2Oct 28
Frequency response .....Jun 26
Input capacitance .....Jun 26
Waveform errors associated with .....Jun 28

WAVEFORMS

Bandpass amplifier response .....Nov 21
Bandwidth of video IF, method used to measure .....Apr 4
Chroma oscillator, in .....Sym Apr 51
Color burst at phase detector .....Jan 53
Color generator, in .....Sym Feb 37
Color killer, in .....Sym Jun 31
Color signal, expanded .....Jun 60
Composite video showing sync defects .....Jan 20
.....Jan 21
Convergence assembly, in ....Sym Mar 45
Demodulator, chroma .....Nov 28
Difference amplifier grids, at .....Sep 33
Doubled-tuned color IF system, responses in .....Nov 51
Hash on defective filter capacitors .....Jan 21
Horizontal keying pulse at burst amplifier grid .....Jan 53
Horizontal linearity poor, effects on waveform .....Jun 28
Horizontal-output system, in .....Sep 10
Horizontal sync and feedback pulses .....Oct. 20
Horizontal sync pulse .....Jan 18
Hum in video IF signal .....Apr 5
IF and chroma response, overall ..Nov 24
IF bandpass curve, in color receiver .....Sep 47
Keyed-rainbow chroma signal.....Nov 26
Low-voltage supply circuits, in....May 28
Musical notes, typical .....May 26
Response curve of video IF peaked, associated with poor picture quality .....Apr 4
Response curves, video IF in color receiver .....Sep 48
Ringing test, scope patterns obtained in .....Sep 14
Rise time, measurement of .....Jun 59
Secondary electrolytic applications, associated with .....May 29
Sine and square waves, hybrid .....Apr 7
Square wave with differentiation, ringing, and overshoot .....Apr 8
Square wave with overshoot .....Apr 8
Square wave with nonsymmetrical overshoot .....Apr 8
Stagger-tuned color IF system, responses in .....Nov 41
Sync circuits, in .....Jul 37
Sync pulses compressed in video IF signal .....Apr 5
Sync separator, at grid and plate of .....Jan 19
Transient responses of lab- and service-type scopes .....Jun 59
Tuner AFC, in (RCA Chassis CTC21C) .....Sym May 41
Tuner signal observed when input is from AM signal generator .....Apr 3
Tuner signal observed when input is from pattern generator .....Apr 3
Vectorgram display of color receiver .....Jun 59
Vertical sync defects .....Jan 21
Vertical sync feedback pulse .....Jan 17
Vertical sync pulse in sync separator .....Jan 19
Vestigal sideband transmission, compensating for .....Jun 7
Video amplifier responses, square and sweep .....Apr 8
Video IF response
—curves, typical .....Jun 8
—effect of misaligned trap .....Jun 9
—effects of misalignment .....Jun 6
—effects of oscillation in video IF strip .....Jun 9
—frequency increase graphs .....Jun 8
—hash in .....Jun 9
Video IF section, signal observed in .....Apr 4
Video IF signal, undistorted .....Apr 5
Video signals, normal and abnormal .....Apr 7
White compression in video signal .....Apr 7

YOKES

Ringing .....Sep 16

INDEX OF TITLES

Annual TV Tube Stock Guide....Apr 24
Antennas Can Add Profits .....Apr 58
Audio Equipment .....Mar 20
DC Voltage Distribution in Transistor Circuitry .....Dec 4
Depreciation Reserves for Equipment .....Jan 26
Electronic Cables .....Feb 19
Electrolytic Capacitors in TV Receivers .....May 27
Electronic Service Shop .....Sep 37
Getting Started in Electronic Organ Servicing .....May 25
Great Blobs of Color .....May 22
Highlights of 1968 B-W TV .....Oct 4
Industrial Electronics Notebook —Part 2 .....Apr 28
Installing Intercom and Music Distribution Systems .....Dec 24
Intermittent and Time Lapse Sync Troubles .....Jan 17
Introduction to FET's .....Sep 34
Keyed AGC—A Review .....Dec 30
Know Your 68 Color Circuits—Part 1 .....Nov 6
Know Your 68 Color Circuits—Part 2 .....Dec 12
Legal Services for Small Retail And Service Firms .....Feb 30
Many Hued Rasters —Part I .....Jul 44
Many Hued Rasters—Part II .....Sep 32
Measuring the Results of Advertising .....Aug 44
Meet A CB Specialist .....Apr 38
Ohm's Law for AC .....Jan 28
Picture Tube or Chassis—Which? .....Apr 20
Protect Your Business From These Credit Abuses .....Oct 52
RC Circuits .....Oct 38
Removing the Barber Pole .....Jan 22
Repairing the Deluxe AM-FM Chassis .....Oct 32
Scope or Meter—Which? .....Jun 25
Scope Probes .....Mar 28
Servicing High-Quality Audio ....Aug 32
Sheet-Beam Demodulators .....Jul 28
Solid-State Color is Here .....Aug 40
Solid-State Deflection Circuits —Part 1 .....Aug 7
Solid-State Deflection Circuits —Part 2 .....Sep 9
Solid-State Stereo Revisited .....Jun 40
Source Guide to Imported Sets ....Feb 28
Sweep Alignment for TV .....Jun 5
Sweeping Color IF Amplifiers ....Nov 41
Sync from Video to Oscillators ....Jul 35
Symbol Standardization .....Jan 1
The Case of the Bifilar Balun .....Jan 24
Thermistors and Varistors in TV .....Jul 30
Transistor Testers .....Mar 24
Transistor TV Techniques .....Jun 36
Troubleshooting RF, IF, and Video With the Oscilloscope .....Apr 1
Twelve Vertical Color Problems ..Nov 33